

CONTRACTOR TO CHECK ALL DIMENSIONS ON SITE BEFORE COMMENCEMENT OF ANY WORKS, ANY ANOMALIES MUST BE REPORTED. DO NOT SCALE FROM

LOCATION PLAN

(NOT TO SCALE)

SITE DEMISE TO BE CONFIRMED.

THIS DRAWING WAS PREPARED USING INFORMATION FROM FAITHFUL & GOULD JOB No.5117654

CONTRACTOR TO CHECK ALL DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORKS. ANY DISCREPANCIES TO BE BROUGHT TO THE ATTENTION OF THE ARCHITECT.

DO NOT SCALE FROM THIS DRAWING, USE ONLY DIMENSIONS SHOWN ON DRAWINGS. DIMENSIONS FIGURED ARE TO THE NEAREST

THE DRAWINGS RELATE TO THE PROPOSED WORKS AT LLANRUMNEY HALL, CARDIFF.

THIS DRAWING IS TO BE CLIENT APPROVED BEFORE COMMENCEMENT OF ANY WORKS.

THE DRAWING HAS BEEN PRODUCED FOR PLANNING PURPOSE ONLY.

ALL DEMOLITION WORKS SUBJECT TO

STRUCTURAL ENGINEERS APPROVAL AND FULL DESIGN AND SPECIFICATION.

NO WORKS TO COMMENCE ON SITE UNTIL FULL PLANNING APPROVAL AND LISTED BUILDING CONSENT HAVE BEEN OBTAINED.

BUILDING CONTROL APPROVAL REQUIRED PRIOR TO COMMENCEMENT OF WORKS ON

**OBTAIN STRUCTURAL ENGINEERS** 

RECOMMENDATIONS TO CHECK AND ADVICE STABILITY OF THE STRUCTURE.

OBTAIN SPECIALIST ADVICE ON BASEMENT FLOODS AND AFFECTING GROUND FLOOR FINISHES. UNDERTAKE WORKS AS ADVISED BY SPECIALIST TO PREVENT BASEMENT FLOODING.

WINDOWS TO BE OVERHAULED. REMOVE ALL EXISTING PAINT, FILL SAND AND APPLY 2 UNDERCOATS AND 2 GLOSS COATS OF

REMOVE ALL DEFECTIVE WALL FINISHES. HACK OFF AND RE RENDER ALL EXISTING LIME RENDERS WHERE DEFECTIVE, FILL PREPARE AND REDECORATE THROUGHOUT USING 2 COATS OF EMULSION PAINT FINISH.

CAREFULLY REPAIR ALL EXISTING CEILINGS WITH MATERIALS TO MATCH THE EXISTING.

CAREFULLY REFIX ALL LOOSE WOODWORK, INCLUDING INTERNAL DOORS, ARCHITRAVES, AND SKIRTING'S, ETC. OVERHAUL ALL DOORS TO ENSURE FULLY FUNCTIONING. PREPARE, FILL AND REDECORATE USING 2 UNDERCOATS AND 2 GLOSS COATS.

REMOVE ALL FIXTURES AND FITTINGS FROM SPECIALIST MOLDED HIGH LEVEL PLASTER. REPAIR DAMAGES AND REDECORATE.

REVISION NOTE: DRAWING STATUS:

REV: C BY: OT CHK: SF DATE: 30.06.2014

DATE: 07.01.2014

DATE: 05.01.2014

EXISTING STAIRCASE TO BE RETAINED.

REV: B BY: OT CHK: SF

REV: A BY: OT CHK: SF

COMMUNITY HALL RELOCATED.

RE-ISSUED FOR PLANNING.

PLANNING

PAINTWORK.

STEVE BORLEY

LLANRUMNEY HALL, BALL ROAD, CARDIFF COMMUNITY AND TRAINING CENTER


## franks + toms ARCHITECTS

PROPOSED SECOND FLOOR PLAN GENERAL ARRANGEMENT

OT SF 06.12.2013 1481 DRAWING NUMBER: | SCALE: 1481-23-202 C 1:100

> Franks and Toms Architects Limited Office 8 St Andrews Crescent, Cardiff, CF10 3DD. T 02920 390099 E info@franksandtoms.com www.franksandtoms.com

EXISTING EXTERNAL WALLS TO MAIN BUILDING ARE SOLID MASONRY, WITH A TEXTURED RENDER AND MASONRY PAINT FINISH. THE RENDER FINISH HAS PREVIOUSLY BEEN REPAIRED IN NUMEROUS LOCATIONS, HAIRLINE CRACKS ARE VISIBLE. CONTRACTOR TO HAMMER TEST ALL AREAS TO IDENTIFY THE DEFECTIVE AREAS. ALL DEFECTIVE AREAS OF RENDER REQUIRE HACKING OFF AND RE-RENDERING TO MATCH EXISTING. TREAT ALL SURFACES TO REMOVE ALGAE, CLEAN ALL EXISTING RENDER SYSTEM, PREPARE AND REDECORATE USING SUITABLE MASONRY PAINT SYSTEM, COLOUR WHITE.



THE EXISTING TIMBER SASH WINDOWS ARE IN POOR DECORATIVE ORDER. MANY HAVE ROTTEN SILLS AND LOWER SASH FRAMES, AND DEFECTIVE PUTTY. CORDS ARE BROKEN, AND SASH UNITS HAVE BEEN PAINTED SHUT, AND SCREW FIXED IN SOME AREAS. ALL EXISTING TIMBER WINDOWS ARE TO BE PROBED TO IDENTIFY DEFECTIVE AREAS. DEFECTIVE AREAS ARE TO BE REPLACED WITH NEW TREATED TIMBER TO MATCH EXISTING. ALL SASH UNITS REQUIRE OVERHAULING TO ENSURE OPERATION, INCLUDING OPENING BOX UNITS, REPLACEMENT OF ALL DEFECTIVE REAR BOX SASH UNITS, CORDS, WEIGHTS, REMOVAL OF SCREWS FIXING SASH WINDOWS, PUTTY AND DECORATION, OVERHAUL IRONMONGERY. REPLACING ANY DEFECTIVE/ MISSING TO MATCH. REMOVE ALL EXISTING PAINT, FILL SAND AND APPLY 2 UNDERCOATS AND 2 GLOSS COATS OF PAINTWORK. REPLACE ANY DEFECTIVE

GLAZED UNITS.

SECOND FLOOR PLAN

(SCALE 1:100 @ A1)